HVU145

Silicon Epitaxial Planar Pin Diode for Antenna Switching

REJ03G0437-0200
(Previous: ADE-208-1508A)
Rev.2.00
Dec 07, 2004

Features

- An optimal solution for antenna switching in mobile phones.
- Low capacitance. (C =0.45 pF max)
- Low forward resistance. (rf = 1.8 Ω max)
- Ultra small Resin Package (URP) is suitable for surface mount design.

Ordering Information

Type No.	Laser Mark	Package Code
HVU145	T5	URP

Pin Arrangement



1. Cathode
2. Anode

Absolute Maximum Ratings

(Ta = 25°C)

Item	Symbol	Value	Unit
Reverse voltage	V_R	60	V
Forward current	I_F	50	mA
Power dissipation	Pd	150	mW
Junction temperature	Tj	125	°C
Storage temperature	Tstg	–55 to +125	°C

Electrical Characteristics

(Ta = 25°C)

Item	Symbol	Min	Typ	Max	Unit	Test Condition
Reverse current	I_R	—	—	100	nA	V_R = 60 V
Forward voltage	V_F	—	—	0.9	V	I_F = 2 mA
Capacitance	C	—	—	0.45	pF	V_R = 1 V, f = 1 MHz
Forward resistance	r_f	—	—	1.8	Ω	I_F = 10 mA, f = 100 MHz
ESD-Capability *[1]	—	100	—	—	V	C = 200 pF, R = 0 Ω, Both forward and reverse direction 1 pulse.

Note: 1. Failure criterion ; I_R > 100 nA at V_R = 60 V

Main Characteristic



Fig.1 Forward current vs. Forward voltage



Fig.2 Reverse current vs. Reverse voltage



Fig.3 Capacitance vs. Reverse voltage



Fig.4 Forward resistance vs. Forward current



Fig.5 Forward resistance (parallel) vs. Forward voltage

Package Dimensions

As of January, 2003

Unit: mm



Package Code	URP
JEDEC	Conforms
JEITA	—
Mass (reference value)	0.004 g

Renesas Technology Corp. Sales Strategic Planning Div. Nippon Bldg., 2-6-2, Ohte-machi, Chiyoda-ku, Tokyo 100-0004, Japan

RENESAS SALES OFFICES

http://www.renesas.com

Refer to "**http://www.renesas.com/en/network**" for the latest and detailed information.

Renesas Technology America, Inc.
450 Holger Way, San Jose, CA 95134-1368, U.S.A
Tel: <1> (408) 382-7500, Fax: <1> (408) 382-7501

Renesas Technology Europe Limited
Dukes Meadow, Millboard Road, Bourne End, Buckinghamshire, SL8 5FH, U.K.
Tel: <44> (1628) 585-100, Fax: <44> (1628) 585-900

Renesas Technology Hong Kong Ltd.
7th Floor, North Tower, World Finance Centre, Harbour City, 1 Canton Road, Tsimshatsui, Kowloon, Hong Kong
Tel: <852> 2265-6688, Fax: <852> 2730-6071

Renesas Technology Taiwan Co., Ltd.
10th Floor, No.99, Fushing North Road, Taipei, Taiwan
Tel: <886> (2) 2715-2888, Fax: <886> (2) 2713-2999

Renesas Technology (Shanghai) Co., Ltd.
Unit2607 Ruijing Building, No.205 Maoming Road (S), Shanghai 200020, China
Tel: <86> (21) 6472-1001, Fax: <86> (21) 6415-2952

Renesas Technology Singapore Pte. Ltd.
1 Harbour Front Avenue, #06-10, Keppel Bay Tower, Singapore 098632
Tel: <65> 6213-0200, Fax: <65> 6278-8001

Colophon .2.0