






TABLE 1

FUNCTION
SIGNAL OUT
CURRENT TORQUE
-15 TO -16.5 VDC
+15 TO +16.5 VDC
NC
TEMP. SENSOR
SELF TEST
GROUND
-10 VDC OUTPUT
+10 VDC OUTPUT



DIRECTION OF SENSITIVITY



PN 979-1500-001

THIS DOCUMENT IS AN UNPUBLISHED WORK. COPYRIGHT 1990, 1994.
HONEYWELL INTERNATIONAL INC. ALL RIGHTS RESERVED.

OUTLINE, ACCELEROMETER
Q-FLEX, HI-G

HONEYWELL INTERNATIONAL INC.
REDMOND, WA 98073-9701

PN 979-1500-001

EXP-004